



# GEOTECHNICAL APPRAISAL : CLIFF COLLAPSE CORNWALL



Earth Environmental & Geotechnical (Southern) Ltd were commissioned to undertake a cliff stability appraisal of a site near Watergate Bay in Newquay, Cornwall.

HM Coastguard had reported a section of the cliff had collapsed in early 2020.

As part of the study, a Phase I Desk Study was carried out, including obtaining a site specific geological and ground stability report.

As part of the appraisal Earth Environmental & geotechnical (Southern) Ltd carried out a site walkover and visual assessment of the cliff instability.

An interpretative report was produced detailing:

- Desk Study Information
- Cliff Stability Appraisal
- Recommendations on further Inspection Works



**CLIENT:** Confidential

**LOCATION:** Whitfield Road Bristol

**VALUE:** Confidential

**ACTIVITIES:** Environmental & Geotechnical Site Investigation

## HEAD OFFICE

Houldsworth Mill Business Centre,  
Houldsworth Street,  
Stockport,  
SK5 6DA

E: [headoffice@earthenvironmental.co.uk](mailto:headoffice@earthenvironmental.co.uk)

T: 0161 975 6088

## SOUTH WEST

Suite F8, Kingsbury House,  
Kingsbury Square,  
Melksham, near Bath,  
SN12 6HL

E: [southwest@earthenvironmental.co.uk](mailto:southwest@earthenvironmental.co.uk)

T: 01225 434237

## SOUTH

200 Brook Drive,  
Green Park,  
Reading, Berkshire,  
RG2 6UB

E: [south@earthenvironmental.co.uk](mailto:south@earthenvironmental.co.uk)

T: 01189 253229

## SCOTLAND

Hudson House,  
8 Albany Street,  
Edinburgh,  
EH1 3QB

E: [scotland@earthenvironmental.co.uk](mailto:scotland@earthenvironmental.co.uk)

T: 0131 564 1789

## NORTH EAST

The Wilton Centre,  
Redcar,  
TS10 4RF

E: [northeast@earthenvironmental.co.uk](mailto:northeast@earthenvironmental.co.uk)

T: 01642 438125